

Insignia

Insignia

OFFICE OF SUB DIVISIONAL ENGINEER, REGIONAL SUB DIVISION, PUBLIC
WORKS DEPARTMENT, BUILDINGS AND ROADS BRANCH MALERKOTLA

To

Principal
Baba Jora Singh Memorial Public School
Gurbaxpura, District Malerkotla

Number : 77

Dated : 19/05/2023



Subject : Regarding issuance of Safety Certificate of Building of School (Baba Jora Singh Memorial Public School, Gurbaxpura, District Malerkotla)

Reference : Your letter no. BJS/SPL/125/2023 Dated 09/05/2023

With reference to the above cited subject and cited letter it is to write that Sh. Manpreet Singh Junior Engineer of this Sub Divisional Office after inspection of your school has reported that the building seems safe from outside upto year 2023-24 (31-03-2024). Apart from this, it is also to write that incase there needs to be any alteration to be made then the same checked from some Technical qualified engineer and get verified. If due to any natural calamity the walls, foundation gets removed then the same be checked from Technical qualified engineer and get verified. Its inspection fee of Rs.10000/- has been got deposited vide G.R. No. 663570 dated 19/05/2023.

sd/-

Sub Divisional Engineer
Regional Sub Division
P.W.D. (B&R)
Branch Malerkotla

sd/-

Endr. No.

Dated :

The copy of the above is forwarded to Executive Engineer, Public Works Division, (B & R) branch Malerkotla for information please.

TRUE TRANSLATION FROM
Punjabi, Hindi, Urdu to English

NOTARY PUBLIC
BARNALA (Pb.) INDIA

23 JUN 2023

sd/-

Sub Divisional Engineer
Regional Sub Division
P.W.D. (B&R)
Branch Malerkotla




**ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,
ਭਵਨ ਤੇ ਮਾਰਗ, ਸ਼ਾਖਾ, ਮਲੇਰਕੋਟਲਾ**

ਵੱਲ ਪ੍ਰਿੰਸੀਪਲ,
ਬਾਬਾ ਜੋਰਾ ਸਿੰਘ ਮੈਮੋਰੀਅਲ ਪਬਲਿਕ ਸਕੂਲ,
ਗੁਰਬਖਸ਼ਪੁਰਾ, ਜ਼ਿਲ੍ਹਾ ਮਲੇਰਕੋਟਲਾ।

ਨੰਬਰ 77 ਮਿਤੀ 19/05/2023
ਵਿਸ਼ਾ: ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਲੈਣ ਸਬੰਧੀ (ਬਾਬਾ ਜੋਰਾ ਸਿੰਘ ਮੈਮੋਰੀਅਲ ਪਬਲਿਕ
ਸਕੂਲ, ਗੁਰਬਖਸ਼ਪੁਰਾ, ਜ਼ਿਲ੍ਹਾ ਮਲੇਰਕੋਟਲਾ)

ਹਵਾਲਾ: ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰ: BJS/SPL/125/2023 ਮਿਤੀ 09/05/2023

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅਤੇ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦਫਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਸ਼੍ਰੀ ਮਨਜੀਤ ਸਿੰਘ ਵੱਲੋਂ ਆਪ ਜੀ ਦੇ ਸਕੂਲ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2023-24 (31-03-2024) ਤੱਕ ਬਾਹਰੋਂ ਵੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਵਿੱਚੋਂ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ਨਲ ਆਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾ ਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਜੇਕਰ ਹੜ੍ਹ, ਕੁਦਰਤੀ ਆਫਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਰਾਂ ਬਹਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਾਉਣ, ਉਪਰੰਤ ਤਸਦੀਕ ਵੀ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਜੀ.ਆਰ.ਨੰ: 663570 ਮਿਤੀ: 19/05/2023 ਰਾਹੀਂ 10,000/- ਰੁਪਏ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ:
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਮਲੇਰਕੋਟਲਾ।
/ 11

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ: ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਲੇਰਕੋਟਲਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

/ 1
ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ:
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਮਲੇਰਕੋਟਲਾ।


Building safety report

NAME OF SCHOOL: BABA JORA SINGH MEMORIAL PUBLIC SCHOOL, GURBAXPURA, DISTT. MALERKOTLA.

As per report of Sh. Manpreet Singh (Junior Engineer) on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:-

1. However, the Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required to be done, regarding this inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained be from the competent Authority.
6. The owner of the building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the building as per Drawing submitted by the owner.
8. This report is not valid for legal purpose.

As per visually inspection as reported by the concerned Junior Engineer the above building may be used for normal use for One year up to 31/03/2024 subject to the above conditions.


Sub-Divisional Engineer,
Provl. Sub- Division,
PWD B&R Malerkotla.